

# 1210\_BASCULA BERRY

## FRONT PART

### 1210\_Báscula Berry Manual de instrucciones (Esp)



Recomendamos que lea detenidamente este manual de instrucciones y lo conserve para futuras consultas.

#### Descripción del producto:



Encendido /Apagado / Unidades

#### Especificaciones:

- Peso máximo soportado: 180kg
- Peso mínimo: 0.2kg
- Precisión: 50g
- Unidades de medida: kg/lb
- Temperatura
- Función auto-encendido/apagado.

#### Funcionamiento:

Introduzca en la báscula 2 pilas AAA y sitúela en una superficie firme y nivelada.

Si desea cambiar la unidad de medida, pulse el botón ON/OFF situado en la parte trasera del dispositivo.

La báscula se encenderá automáticamente cuando coloque un peso superior a 4kg. La pantalla mostrará el peso, la temperatura y el nivel de batería del dispositivo.

La pantalla se apagará automáticamente tras 15 segundos.

#### Advertencias:

1. No lo exponga a la lluvia o entornos mojados.
2. Evite caídas que le puedan generar daños serios.
3. No intente reparar la unidad por sí mismo, contacte con un especialista.
4. Para evitar riesgos, no se deshaga de él de manera inapropiada.
5. Límpielo con un trapo seco.
6. No lo instale cerca de fuentes de calor o luz solar directa.
7. No inserte ningún objeto metálico en la unidad, existiría la posibilidad de un cortocircuito.



El símbolo de referencia tanto en el producto como en su manual de usuario, indica que al final de la vida útil de los aparatos eléctricos y/o electrónicos, éstos deberán reciclarse por separado de sus residuos domésticos. Existen medios adecuados para recoger este tipo de material para su correcto reciclaje.

Para obtener más información, póngase en contacto con la autoridad local.

MKTO CATAL IMPORTACIONES S.L. B04267225  
Ctra. De Huercal-Óvera, s/n. 04640, Pulpi, Almería, Spain.



MADE IN PRC

## BACK PART

### 1210\_Weighing Scales Berry User manual(Eng)



It is recommended to read this user manual carefully and keep it for future reference.

#### Product overview:



ON/OFF / Units

#### Specifications:

- Maximum capacity: 180kg
- Minimum capacity: 0.2kg
- Accuracy: 50g
- Units of measurement: kg/lb
- Temperature
- Auto power ON/OFF function

#### Operation:

Insert 2 button batteries AAA and place the scale onto a firm level surface.

To change the measurement units, press the ON/OFF button.

The scale will turn on automatically with a weight higher than 4kg. The screen will show the weight, the temperature and the battery level.

The screen will turn off automatically after 15 seconds.

#### Warnings:

1. Do not expose this product to rain or damp conditions.
2. Prevent this item from falling as it could cause serious damage.
3. Do not dismantle, repair or modify this product by yourself, contact an authorized specialist.
4. In order to avoid any risk, do not dispose of this product inappropriately.
5. Clean it with a dry cloth.
6. Do not place this item near sources of heat or expose to direct sunlight.
7. Do not insert any metal objects into this device as there is a risk of causing a short circuit in the unit.



This symbol both in the product and its user manual indicates that at the end of the devices electrical life, it should be recycled separately from your household waste. There are adequate means to dispose of this material for proper recycling. For more information, contact your local authorities.

MKTO CATAL IMPORTACIONES S.L. B04267225  
Ctra. De Huercal-Óvera, s/n. 04640, Pulpi, Almería, Spain.



MADE IN PRC