

21234_BÁSCULA CUCHARA LANGEK

FRONT PART

21234 - Báscula Cuchara Langek Manual de instrucciones (Esp)



Recomendamos que lea detenidamente este manual de instrucciones y lo conserve para futuras consultas.

Especificaciones:

- Unidades de medida: g, ml, oz.
- Alimentación: 1 Pila CR2032 Incluida.

Funcionamiento:

- Pulse el botón ON/TARE para encender la báscula. Manténgalo pulsado para apagarla.
- Mantenga pulsado el botón UNIT para cambiar la unidad de medida.
- Función Tara: Pese el primer elemento y pulse el botón TARA. El marcador se pondrá a cero y podrá añadir el siguiente elemento para ver su peso.
- Función Hold: Pese el primer elemento y pulse el botón HOLD. El marcador se pondrá a cero y podrá añadir el siguiente elemento para ver el peso conjunto.

Notas de uso:

- El peso máximo soportado por la báscula es de 300 g. Si se intenta pesar cualquier objeto por encima de este peso, la pantalla LCD mostrará el mensaje ERR. Además, se corre el riesgo de dañar la báscula.
- Para asegurar una medición de peso precisa, se recomienda no balancear ni mover en exceso el objeto a pesar durante el proceso de medición.
- NO mantener durante mucho tiempo el objeto a pesar en el aire, ya que podría dañar la báscula.
- Para asegurar la precisión en la medición del peso, NO usar el dispositivo cerca de campos magnéticos.

Advertencias:

1. No lo exponga a la lluvia o entornos mojados.
2. Evite caídas que le puedan generar daños serios.
3. No intente reparar la unidad por sí mismo, contacte con un especialista.
4. Límpielo con un trapo seco.
5. No lo instale cerca de fuentes de calor o luz solar directa.
6. No inserte ningún objeto metálico en la unidad, existiría la posibilidad de un cortocircuito.
7. Mantener fuera del alcance de los niños

CE
FABRICADO EN PRC



El símbolo de referencia tanto en el producto como en su manual de usuario, indica que al final de la vida útil de los aparatos eléctricos y/o electrónicos, éstos deberán reciclarse por separado de sus residuos domésticos. Existen medios adecuados para recoger este tipo de material para su correcto reciclaje. Para obtener más información, póngase en contacto con la autoridad local. Antes de entregar los RAEE se deben extraer las pilas.

MKTO CATAL IMPORTACIONES S.L. B04267225
Ctra. de Huercal-Overa, s/n. 04640, Pulpi, Almería, Spain.

BACK PART

21234 - Weighing Scale Langek User manual (Eng)



It is recommended to read this user manual carefully and keep it for future reference.

Specifications:

- Unit: g, ml, oz
- Power: 1 Button battery Cr2032 Included.

Operation:

- Press ON/TARE button to turn the scale on. Hold to turn off.
- Hold UNIT button to change the unit of measurement.
- Tara function: Weight the first item and press TARA button. The marker will reset to zero and you can add next item to see its weight.
- Hold function: Weight the first item and press the HOLD button. The marker will reset to zero and you can add next item to see the overall weight.

Usage notes:

- The maximum weight limit for this scale is 300 g. If objects heavier than 50kg are placed on the scale, the display will show ERR message. Attempting to weigh items over 50kg could damage the scale.
- To ensure the highest accuracy possible, avoid shaking or rocking while weighing items in the scale.
- DO NOT stress the triangle ring for long time.
- To ensure accuracy, DO NOT use this scale near strong magnetic fields.

Warnings:

1. Do not expose this product to rain or damp conditions.
2. Prevent this item from falling as it could cause serious damage.
3. Do not dismantle, repair or modify this product by yourself, contact an authorized specialist.
4. Clean it with a dry cloth.
5. Do not place this item near sources of heat or expose to direct sunlight.
6. Do not insert any metal objects into this device as there is a risk of causing a short circuit in the unit.
7. Keep the scale away from children.

CE
MADE IN PRC



This symbol both in the product and its user manual indicates that at the end of the devices electrical life, it should be recycled separately from your household waste. There are adequate means to dispose of this material for proper recycling. For more information, contact your local authorities. Before disposing of the WEEE, please remove the batteries.

MKTO CATAL IMPORTACIONES S.L. B04267225
Ctra. de Huercal-Overa, s/n. 04640, Pulpi, Almería, Spain.